

## DIAMONDS

Your browser does not support the video tag.

### DIAMONDS

#### Origin

diamonds can be mined where you find the mountain type kimberlit, you need to mine approx. 2 tonnes to find 1 carat of diamond = 0,2 g.

20% of the production world wide is used for jewellery. the rest is used in the industry for drilling, milling and grinding.

#### Quality

##### the four Cs

#### CARAT

measure for weight: 1 carat = 0.2 gram

the availability of diamonds is very much depending on the size - the bigger the diamond, the harder to get

the price of a diamond is a function of size, but rises exponentially!

#### CUT

##### brilliant

#### The ideal angle of the cut

**COLOUR**

**CLARITY**

**LINDBERG diamonds**

Carat: 0.01 0.02 0.03 Ct.


Cut: brilliant

Colour: top Wesselton/G

Clarity: VVS very very small inclusions

**we only use top quality diamonds.**

[Download file PDF](#)



isoptik.com